

ENGINE

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Diesel Injection System	Diesel Injection Pump	○				○		
	Diesel Injectors	○				○		
	Timing Device		○			○		
	Timing Chain		○				○	
	Chain Tensioner	○					○	
	Diesel Emission			○		○		
	Rod Assy for Injection Control		○				○	
	Engine Idle Speed Condotion			○			○	
	Max Speed			○			○	
	Max RPM			○			○	
	Accelerator Pedal			○		○		
	Overall Performance					○		
Cooling System	Belt Tensioner		○			○		
	Idle Bering		○				○	
	Tension Bering		○				○	
	Tension Spring		○			○		
	Teension Shock Absorbor		○			○		
	Belt		○			○		
	Viscos Fan Cluth		○			○		
	Thermostat		○			○		
	Water Pump			○				○
	Coolant		○				○	
	Coolant Hoses		○				○	
	Radiator for Water Cooling			○				○
	Overall Performance					○		

ENGINE

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Engine Electric System	Alternator		○			○		
	Starter			○				○
	Glow Plug		○				○	
	Glow Plug Relay		○			○		
	Battery			○				○
	Engine Wiring Harness			○				○
	Overall Performance					○		
Air Conditioning System	Compressor for Aircon			○				
	Heater			○				
	PNL ASSY for Heater control			○				
	Aircon Gas			○				
	Overall Performance							
Exhaust System	Turbo Charger			○			○	
	EGR			○			○	
	Exhaust Pipe			○			○	
	Overall Performance						○	

TRANSMISSION

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Transmission	Shift Up & Down			○			○	
	Oil filter & Pan Gasket		○				○	
	Overall Performance						○	

SUSPENSION

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Suspension	Ball Joint/ FRT Upper & Lower		○			○		
	Track Control Arm/ FRT Upper			○			○	
	Track Control Arm/ FRT Lower			○			○	
	Torsion Bar Spring/ FRT		○				○	
	Coil Spring/ RR		○				○	
	Shock Absorber/ FRT		○			○		
	Shock Absorbor/ RR		○			○		
	5-lilnks Suspension/ RR		○				○	
	Link/ Stabilizer		○			○		
	Bush/ Stabilizer		○				○	
	Overall Performance					○		

CHASSIS

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Chassis	Axle Shaft for 4WD/ FRT	○					○	
	Wheel Bearing/ FRT	○					○	
	Knuckle			○			○	
	Seal/ FRT Knuckle		○				○	
	Propeller Shaft/ FRT			○			○	
	Propeller Shaft/ RR			○			○	
	Transfer Case	○					○	
	T/C Motor			○			○	
	4 Wheel Drive			○			○	
	Steering Gear Assy			○			○	
	Ball Joint/ Tie Rod		○			○		
	Wheel Alignment			○			○	

CHASSIS

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Chassis	Tire			○				
	Wheel Disk			○				
	Overall Performance						○	

BRAKE

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Brake	Brake Disk/FRT		○				○	
	Brake Disk/ RR			○			○	
	Brake Pad Set/ FRT		○			○		
	Brake Pad Set or Shoe Set/ RR			○			○	
	Brake Caliper/ FRT			○			○	
	Brake Caliper or Drum/ RR			○			○	
	Brake Hose/ FRT			○			○	
	Brake Hose/ RR			○			○	
	Brake Fluid		○				○	
	Vacuum Pump			○			○	
	Master Cylinder			○			○	
	Booster			○			○	
	Overall Performance						○	

BODY

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Interior	Power Window			○			○	
	Window Switch			○			○	
	Actuator for Auto Door Lock			○			○	
	Audio			○			○	
	Front Seat		○			○		
	Reae Seat		○			○		
Exterior	Door			○			○	
	Hood(Bonnet)			○			○	
	Bumper/ FRT & RR			○			○	
	Roof			○			○	
	Underbody Corrosion			○				○
	Luggage Deck			○				○
Lights	Headlight			○				○
	Tail light			○				○
	Licence Plate Light			○				○
	Stop Light			○				○
	Reverse Light			○				○
	Door Light			○				○
	Instrument Light			○				○
	Pushbutton Switch Bulb			○				○
	Overall Performance							○

OILS

Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Oils	Engine Oil		○			○		
	Transmission Oil		○			○		
	Axle Oil/ FRT		○			○		
	Axle Oil/ RR		○			○		
	Transfer Case Oil		○			○		
	Power steering Oil		○			○		
Overall Performance						○		

FILTERS


Description		Repair				Working condition		
		○ Rebuilt	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Filters	Engine Oil Filter		○			○		
	Air Filter		○			○		
	Cabin Filter		○				○	
	Transmission Oil Filter		○				○	
	Overall Performance						○	

Special options

Description		Repair				Working condition		
		○ Added	○ Replaced	○ Checked	○ None	○ Exceed OE Quality	○ OE quality	○ Aftermarket Quality
Special options	ATF Cooler by Air Cooling				○	○		
	Upgraded Driver's Seat		○			○		
	Upgraded Passenger's Seat		○			○		
	Upgraded Rebuilt Bosch Alternator		○			○		
	The function of Heated Seats	○						
	Overall Performance							

Eterior body damage diagram

- New Panel Fitted
- Broken
- Crack
- Dent
- Repair
- Scratch
- Chip
- Re-Painted
- Faded



KoreaSUV'S Report